

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator ID Number K51007246845	2. Page 1 of 1	3. Emergency Response Phone (800) 462-5716	4. Manifest Tracking Number <b>008037706 FLE</b>		
5. Generator's Name and Mailing Address Clean Harbors Env Services LLC 2549 North New York Street Wichita, KS 67219 (316) 268-7400			Generator's Site Address (if different than mailing address) SAME				
6. Transporter 1 Company Name Waste Transfer			U.S. EPA ID Number K000000000				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Harbors Env Services Inc 2247 South Highway 71 Kimball NE 68145 Facility's Phone: (308) 235-4012			U.S. EPA ID Number NE0981723513				
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
	1.	HAZ077, HAZARDOUS WASTE, SOLID, N.O.S., (TOLUENE, LEAD), S.H.G III	1	07	12	Y	<div style="display: flex; justify-content: space-between;"> <div>D004 D005 D007</div> <div>D008 D039 D040</div> </div>
	2.						
	3.						
4.							
14. Special Handling Instructions and Additional Information 1. CHAS1806X08 2. HCS171 3. TRUCK 4. CRNTN							
15. <b>GENERATOR'S/OFFEROR'S CERTIFICATION:</b> I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offoror's Printed/Typed Name John H. Brown				Signature <i>John H. Brown</i>		Month Day Year # 2 9 15	
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:						
	Transporter signature (for exports only):						
DESIGNATED FACILITY	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name Johnny Thomas		Signature <i>Johnny Thomas</i>		Month Day Year 2 9 15		
	Transporter 2 Printed/Typed Name		Signature		Month Day Year		
18. Discrepancy							
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection							
Manifest Reference Number:							
18b. Alternate Facility (or Generator)						U.S. EPA ID Number	
Facility's Phone:							
18c. Signature of Alternate Facility (or Generator)						Month Day Year	
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H040		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name				Signature		Month Day Year	

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator ID Number <b>KSD007246846</b>	2. Page 1 of <b>1</b>	3. Emergency Response Phone <b>(800) 483-3718</b>	4. Manifest Tracking Number <b>008037706 FLE</b>		
5. Generator's Name and Mailing Address <b>Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219 Generator's Phone: (316) 269-7400</b>				Generator's Site Address (if different than mailing address) <b>SAME</b>			
6. Transporter 1 Company Name <b>Neve Inc</b>				U.S. EPA ID Number <b>IND984868406</b>			
7. Transporter 2 Company Name				U.S. EPA ID Number			
8. Designated Facility Name and Site Address <b>Clean Harbors Env Services Inc 2247 South Highway 71 Kimball, NE 69145 Facility's Phone: (308) 235-4012</b>				U.S. EPA ID Number <b>NED981723513</b>			

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
		No.	Type			D004	D005	D007
<b>X</b>	<b>1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (TOLUENE, LEAD), 9, PG III</b>	<b>1</b>	<b>DT</b>	<b>EST 12</b>	<b>Y</b>	<b>D008</b>	<b>D039</b>	<b>D040</b>

14. Special Handling Instructions and Additional Information  
**1. CH831506X0B**      **ERG#171**      **TRUCK #**      **CHRT #**  

**101**
**B**
**24433**

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.  
 I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offoror's Printed/Typed Name <b>Jim tyson</b>	Signature 	Month <b>2</b>	Day <b>9</b>	Year <b>15</b>
--	---------------	-------------------	-----------------	-------------------

16. International Shipments    ☐ Import to U.S.    ☐ Export from U.S.    Port of entry/exit: \_\_\_\_\_  
 Transporter signature (for exports only): \_\_\_\_\_    Date leaving U.S.: \_\_\_\_\_

17. Transporter Acknowledgment of Receipt of Materials				
Transporter 1 Printed/Typed Name <b>Jimmy Thomas</b>	Signature 	Month <b>2</b>	Day <b>9</b>	Year <b>15</b>
Transporter 2 Printed/Typed Name	Signature	Month	Day	Year

18. Discrepancy  
 18a. Discrepancy Indication Space    ☐ Quantity    ☐ Type    ☐ Residue    ☐ Partial Rejection    ☐ Full Rejection  
 Manifest Reference Number: \_\_\_\_\_

18b. Alternate Facility (or Generator)		U.S. EPA ID Number	
Facility's Phone:			
18c. Signature of Alternate Facility (or Generator)		Month	Day

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1. <b>H040</b>	2.	3.	4.
----------------	----	----	----

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a

Printed/Typed Name <b>Thomas Clerk</b>	Signature 	Month <b>10</b>	Day <b>18</b>	Year <b>15</b>
---	---------------	--------------------	------------------	-------------------

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator ID Number <b>KSD007246846</b>	2. Page 1 of <b>1</b>	3. Emergency Response Phone <b>(800) 483-3718</b>	4. Manifest Tracking Number <b>008037706 FLE</b>		
5. Generator's Name and Mailing Address <b>Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219 (316) 269-7400</b>				Generator's Site Address (if different than mailing address) <b>SAME</b>			
6. Transporter 1 Company Name <b>Nepco Inc</b>				U.S. EPA ID Number <b>IND984868406</b>			
7. Transporter 2 Company Name				U.S. EPA ID Number			
8. Designated Facility Name and Site Address <b>Clean Harbors Env Services Inc 2247 South Highway 71 Kimball, NE 69145 (308) 235-4012</b>				U.S. EPA ID Number <b>NED981723513</b>			
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
	1	<b>HA3077, HAZARDOUS WASTE, SOLID, N.O.S., (TOLUENE, LEAD), 9, PG III</b>	1	OT	EST 12	Y	<b>D004 D005 D007 D008 D035 D040</b>
	2.						
	3.						
4.							
14. Special Handling Instructions and Additional Information <b>101 B 24433</b>							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offeror's Printed/Typed Name <b>Jim tyson</b>				Signature <i>Jim tyson</i>		Month Day Year <b>02 9 15</b>	
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:						
	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name <b>Jimmy Thomas</b>				Signature <i>Jimmy Thomas</i>		Month Day Year <b>02 9 15</b>
Transporter 2 Printed/Typed Name				Signature		Month Day Year	
DESIGNATED FACILITY	18. Discrepancy						
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	Manifest Reference Number:						
	18b. Alternate Facility (or Generator) U.S. EPA ID Number						
	Facility's Phone:						
18c. Signature of Alternate Facility (or Generator) Month Day Year							
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. <b>H040</b>		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name <b>Thomas Clark</b>				Signature <i>Thomas Clark</i>		Month Day Year <b>02 16 15</b>	



2247 South Highway 71  
Kimball, NE 69145

TEL 308-235-4012  
FAX 308-235-4307  
[www.cleanharbors.com](http://www.cleanharbors.com)

DATE: 2/10/2015

MANIFEST: 008037706FLE

Dear Valued Customer:

In accordance with 40 CFR 264.12(b), Clean Harbors Environmental Services, Inc., Kimball Facility, has appropriate state and federal permits to accept, store, and/or treat the waste you shipped to our facility. This letter should be kept on file with your copy of the signed manifest.

Clean Harbors Environmental Services, Inc. makes every effort to ensure that signed copies of manifests are returned to the waste generator as quickly as possible following receipt of your waste at our facility. This allows us to provide you with rapid verification that your waste shipment arrived safely at our waste management facility.

Once your waste has been received, Clean Harbors' personnel will verify that the quantity that has been received matches the quantity that was shipped. We also inspect the material and conduct testing to ensure that it meets the facility's waste acceptance criteria as described in our Waste Analysis Plan, as well as processing requirements. Every effort is made to complete the waste verification as quickly as possible; however, it is possible that the signed copy of the manifest may be returned to you before the waste verification process is completed. If a significant discrepancy, as defined by US EPA regulations (40 CFR 264.72), is discovered during the waste verification process, we will contact you in order to reconcile the discrepancy. Additionally, we will work with you to make any corrections to the waste manifest that are necessary.

Sincerely,

Receiving Department